



JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report
Minerals Regulatory Program
Report Date: October 26, 2006

Supervisor 1024

Mine Name: Sliver 1-2
Operator Name: Penney's Gemstones, LLC
2400 E 30 S
Box 312
Beaver, UT 84713-0312

Permit number: S/001/035
Inspection Date: October 16,
2006
Time: 5:00 pm to 5:05 pm

Inspector(s): Daron Haddock and Dan Smith
Other Participants: none
Mine Status: Active

Weather: few clouds, cool

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection: Routine inspection while in the area.

Directions to Site: Take dirt/gravel road immediately north of Minersville. Go approximately 3.5 miles to mine site.

Inspection Summary: No activity is occurring at the site nor has there been any recent activity. The site remains the same as it was over a year ago when I last visited the site with a large pit excavated and a large rock face left exposed. I did not see any evidence of environmental harm or degradation occurring.

Conclusions and Recommendations:

The Division should continue to monitor the site. Reclamation should be considered if no mining is planned for the area.

Inspector's Signature

Daron R. Haddock

Date:

10/26/2006

drh:pb

cc: Operator
BLM

P:\GROUPS\MINERALS\WP\M001-Beaver\S0010035-Sliver1-2\inspections\insp-10162006.doc

Mine Number: S0010035

Mine Name: Silver 1-2

Township 29 S Range 09 W Section 20 SLBM

Inspection Date Oct. 16, 2006
Map Produced by DKS

Acres Disturbed	2.49
Acres Regraded	0
Acres Seeded	0
Road Acres Disturbed	0


Total Acres Disturbed	2.49
-----------------------	------

Acres Released	0
Acres Excluded	0
Acres PreExisting	0
Acres Prelaw	0

Legend
All items symbolized in legend may not be appear on map

- County Boundary
- Acres
- Mine
- Northline
- Reclaimed
- Other
- Intermittent
- US Route
- State Route
- Primary Route
- Secondary Route
- Main Dirt Road
- Unimproved Road
- Interchange
- Tail
- Township or range line
- Section line
- Section line location doubtful
- Disturbed
- Regraded
- Seeded
- Released
- Excluded
- PreExisting
- Prelaw
- Bond Area
- STLA Mineral Leases
- BLM Goldminerals
- Community
- STLA Mineral Ownership

DOQ imagery date 2004



0 625
Feet
1:7,500 1 inch equals 625 feet
Verify Scale

Different data sources and input scales
may cause misalignment of data layers.
This product may not meet USGS
standards for accuracy and content.

Dept. of Natural Resources
Division of Oil, Gas, and Mining
Mineral Mines Program

